

Fluke 789 ProcessMeter™


FLUKE®

Double Your Power

The Fluke 787 was the first tool to combine a DMM and a loop calibrator to give process technicians double the power in one tool. Now it's even better, the range is extended with the new Fluke 789 – the ultimate loop calibration multimeter.

The Fluke 789 has a 24-Volt loop supply reducing the need for taking a separate power supply when doing offline transmitter testing. And with its built-in, selectable 250-Ohm Hart® resistor, it also eliminates the need to carry a separate resistor with you.

Now process technicians can do a lot more while carrying a lot less.



New Features of the Fluke 789:

- 24 V Loop power supply
- Very large dual display
- Enhanced backlight with 2 brightness settings
- 1200 Ohm drive capability on mA source
- HART mode setting with loop power and a built-in 250 ohm resistor
- 0% and 100% buttons to toggle between 4 and 20 mA sourcing for a quick span check
- Externally accessible fuses for easy replacement
- Infrared serial I/O port compatible with FlukeView Forms (V2.1) software

These Fluke 789 features are also included in the Fluke 787:

- DMM designed to meet 1000 V EN61010-1 Cat III standards
- Precision 1000 V, 440 mA True-RMS digital Multimeter
- Frequency measurement to 20 kHz
- Min/Max/Average/Hold/Relative modes
- Diode Test and Continuity Beeper
- Simultaneous mA and % of scale readout
- 20 mA DC current source / loop calibrator / simulator
- Manual Step (100%, 25%, Coarse, Fine) plus Auto Step and Auto Ramp
- Externally accessible battery for easy battery changes



LISTED



Measurement Function	Range and Resolution	Best Accuracy (% of reading + LSD)
VDC	400.0 mV, 4.000 V, 40.00 V, 400.0 V, 1000 V	0.1% + 1
VAC (true RMS)	400.0 mV, 4.000 V, 40.00 V, 400.0 V, 1000 V	0.7% + 2
mADC	30.000 mA	0.05% + 2
A DC	1.000 A (0.440 A continuous)	0.2% + 2
A AC	1.000 A (0.440 A continuous)	1% + 2
Resistance	400.0 ohms, 4.000 k, 40.00 k, 400.0 k, 4.0 M, 40 M	0.2% + 1
Frequency (0.5 Hz to 20 kHz)	199.99 Hz, 1999.9 Hz, 19.999 kHz	0.005% + 1
Diode Test	2.400 V (shows diode voltage drop)	2% + 1
Continuity	Beeps for resistance < approx 100 ohms	

Output Function	Range and Resolution	Drive Capability	Accuracy (% of span)
DC Current Output (Internal battery operation)	0.000 to 20.000 mA or 4.000 to 20.000 mA (selectable at power-up) Over-range to 24.000 mA	24 V compliance, or, 1,200 Ohms, @ 20 mA	0.05%
DC Current Simulate (Ext. 24 Volt loop supply)	0.000 to 20.000 mA or 4.000 to 20.000 mA, (selectable at power-up) Over-range to 24.000 mA	1000 Ohms, @ 20 mA	0.05%
24 V Loop Supply Current adjustment modes	Minimum 24 V Manual: Coarse, Fine, 25% and 100% step Automatic: Slow Ramp, Fast Ramp, 25% step	250 Ohms @ 20 mA	> 24 V

Temperature range of 18 °C to 28 °C, for one year after calibration

General Specifications:

Maximum voltage applied between any jack and Earth Ground: 1000 V RMS

Storage Temperature: -40 °C to 60 °C

Operating Temperature: -20 °C to 55 °C

Temperature Coefficient:

0.05 x (specified accuracy) per °C
(for temperatures < 18 °C or > 28 °C)

Relative Humidity: 95% up to 30 °C;
75% up to 40 °C; 45% up to 50 °C; 35%
up to 55 °C

Vibration: Random, 2 g, 5-500 Hz.

Shock: 1 meter drop test

Safety: Designed in accordance with
EN61010, ANSI/ISA S82.01-1994 and
CAN/CSA C22.2 No. 1010.1-92

Over-voltage Category III

Size (HxWxD): 203 x 100 x 50 mm

Weight: 600 g

Battery: Four AA Alkaline battery

Battery Life: 50 hours typical
(measurement), 12 hours typical
(sourcing 12 mA)

Warranty: 3 years

Optional accessories

80T-IR Infrared Temperature Probe
80TK Thermocouple Module
80T-150U Universal Temperature Probe
TL20 / TL22 / TL24 / TL 26 / TL28 /
TL70A / TL40A Test Lead Sets
AC20 / AC80 Clips
TP20 Industrial Test Probes
80i-400 AC Current Clamp
i-410 AC/DC Current Clamp
i-1010 AC/DC Current Clamp
C125 Soft Meter Case
80K-6 and 80K-40 High Voltage Probes
PV350 Pressure Vacuum Module
Fiber Optic Meter FOM
LockPak
ToolPak

Ordering Information

Fluke 789 ProcessMeter

Included Accessories

TL71 Premium Test Lead Set plus
AC72 Alligator Clips
Four AA 9 V alkaline battery (installed)
Users Manual and Quick Reference Guide

Fluke. Keeping your world
up and running.

Fluke Corporation

P.O. Box 9090

Fluke Europe B.V.

P.O. Box 1186
5602 BD Eindhoven
The Netherlands

For more information call:

In the U.S.A. (800) 443-5853

or Fax (425) 446-5116

In Europe/M-East/Africa +31 (0)40 2 675 200

or Fax +31 (0)40 2 675 222

In Canada (905) 890-7600

or Fax (905) 890-6886

From other countries +1 (425) 446-5500

or Fax +1 (425) 446-5116

Visit us on the world wide web at:

<http://www.fluke.com>

Fluke (UK) Ltd

52 Hurricane Way

Norwich

Norfolk

NR6 6JB

Tel 0207 942 0700

Fax 0207 942 0701

Visit us on the world wide web at:

<http://www.fluke.co.uk>